

DC Jack



Difficulty	Moderate
Steps	2
Time Required	5 - 10 minutes

Introduction

If the bike has power going to it but the monitor is not coming on, there may be a loose connection within the DC power jack.

Tools

- 6 mm Allen Wrench
- 3/8in Drive Ratchet
- 3/8in Drive 15 mm Socket

Step 1 - Process Steps





- Flip the bike upwards to rest on the handlebars.
- Remove the rear stabilizer using a 6mm Allen wrench.



- Remove rubber from the outside of the DC jack and remove the nut from the inside of the assembly using a 15mm socket.

Step 2 - Process Steps



- Unplug both connections within the DC jack assembly (male and female connectors).



- Install the new component and reassemble. Be careful not to damage wires during assembly.



- Power on the test the bike to ensure power issues are resolved.